


Assembly drawing: P0055 (A0199-040)


This side should not be connected.
Only sockets crimps on.
Pos. 3, 7, 9 and marking should be send with in a plastic bag.

P0055 (Short and long arm)
Cable I0602 (8x2x0,5) or I0755 (7x2x0,5)



Connected to Circuit diagram E0199-001
Connected to Circuit diagram E0199-002
Connected to Circuit diagram E0199-003

Connected to Circuit diagram E0214-111
Connected to Circuit diagram E0214-105
Connected to Circuit diagram E0214-026

Designed by OHK	Description Upperarm cable, connection box to tool system		
Date 2006-01-04	Description IRB4400/L30, 45, 60, S		
Approved by OHK	Format A3		Page (No. of pages) 01 (01)
		Document no. (filename) P0055E (E0199-004)	Rev. D

We reserve rights in this document and in the information contained therein. It is strictly forbidden to reproduce, disseminate or use it without express authority from Robot System Products.